

	:(2000)	:(2200)	:(2240)	:(2241)	:(120)	[]	(:)
2000		8,220,760	24,753,426	16,532,666	[630,000]	[2,100,000]			
2200		8,220,760	24,753,426	16,532,666	[630,000]	[2,100,000]			
2240		8,220,760	24,753,426	16,532,666	[630,000]	[2,100,000]			
2241		4,242,990	13,110,218	8,867,228	[2,100,000]					
100		153,926	55,460	98,466						
120		153,926	55,460	98,466						
201		144,910	49,448	95,462						
		144,910	49,448	95,462	01					
					○			=		5,957
					○			=		102,485
								=		4,968
								=		29,000
								=		2,500
202		9,016	6,012	3,004						
		9,016	6,012	3,004	01					
								=		9,016
200		4,089,064	13,054,758	8,965,694	[2,100,000]					

: (2000) : (2200) : (2240) : (2242) : (210) [] (:)

					(872,469)
					() 900,000,000 X 99.37/100 = 894,330 (630,000) (264,330)
	11,201	11,092	109	03	(,) 878,000,000 X 0.63/100 = 5,531 (5,531)
					() 900,000,000 X 0.63/100 = 5,670 (5,670)
220	2,008,760	1,568,360	440,400		
206	4,360	1,360	3,000		
	4,360	1,360	3,000	00	= 4,360
207	18,400	7,000	11,400		
	18,400	7,000	11,400	01	(, , ,) 4,600,000 X4 = 18,400
401	1,986,000	1,560,000	426,000		
	1,973,417	1,553,412	420,005	01	

: (2000) : (2200) : (2240) : (2242) : (220) [] (:)

				(L=100m, D=800mm) 30,000,000 X 98.92/100 = 29,676
				(L=250m, D=800mm) 40,000,000 X 98.92/100 = 39,568
				(L=200m, D=500mm) 30,000,000 X 98.92/100 = 29,676
				(L=400m, D=300mm) 40,000,000 X 98.92/100 = 39,568
				(L=400m, D=600mm) 40,000,000 X 98.92/100 = 39,568
				50,000,000 X 98.92/100 = 49,460
				30,000,000 X 98.92/100 = 29,676
				(L=250m, D=400mm) 50,000,000 X 98.92/100 = 49,460
				(L=150m, D=600mm) 36,000,000 X 98.92/100 = 35,612
				(L=400m, D=300mm) 35,000,000 X 98.92/100 = 34,622
	12,583	6,588	5,995	03
				(L=4000m, D=300mm) 150,000,000 X 0.72/100 = 1,080

: (2000) : (2200) : (2240) : (2242) : (220) [] (:)

				199		
					650,000,000	X 0.63/100 = 4,095
					(L=400m, D=600mm)	
					50,000,000	X 1.08/100 = 540
					(L=300m, D=500mm)	
					40,000,000	X 1.08/100 = 432
					(L=200m, D=500mm)	
					30,000,000	X 1.08/100 = 324
					(L=200m, D=600mm)	
					30,000,000	X 1.08/100 = 324
					(L=400m, D=400mm)	
					40,000,000	X 1.08/100 = 432
					(L=200m, D=500mm)	
					30,000,000	X 1.08/100 = 324
					(L=250m, D=400mm)	
					25,000,000	X 1.08/100 = 270
					(L=100m, D=380mm)	
					30,000,000	X 1.08/100 = 324
					(L=300m, D=600mm)	
					30,000,000	X 1.08/100 = 324
					(L=100m, D=800mm)	
					30,000,000	X 1.08/100 = 324
					(L=250m, D=800mm)	
					40,000,000	X 1.08/100 = 432

	: (5000)	: (5100)	: (5110)	: (5111)	: (310)	[(:)]
5000		316,000	211,000	105,000	[316,000]	
5100		316,000	211,000	105,000	[316,000]	
5110		316,000	211,000	105,000	[316,000]	
5111		316,000	211,000	105,000	[316,000]	
300		316,000	211,000	105,000	[316,000]	
310		316,000	211,000	105,000	[316,000]	
311		316,000	211,000	105,000		
		316,000	211,000	105,000	06	
						316,000,000 X 1 = 316,000 (316,000)