

[별첨1] 측정 위치도(측정 장소)

이순신광장로 135-1, 135 석면철거공사



범례	*NO	
	시료채취	부지경계선

[별첨3] 측정 사진

이순신광장로 135-1, 135 석면철거공사			
			
*1. 부지경계선1	*2. 부지경계선2	*3. 부지경계선3	*4. 부지경계선4
			
*5. 위생설비입구	*6. 작업장주변1	*7. 갱의실입구	*8. 음압기배출구
			
*9. 폐기물반출구	*10. 작업장주변2	*11. 작업장주변3	*12. 폐기물보관1
			
*13. 폐기물보관2	-	-	-

[별첨2] 측정 결과

측정위치		측정시간(분)	유량(ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과 여부
*1	부지경계선1	8:33 ~ 12:38	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	8:35 ~ 12:40	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	8:41 ~ 12:46	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	8:44 ~ 12:49	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	8:48 ~ 9:30	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변1	8:51 ~ 10:56	10.00	불검출[검출한계 0.002미만]	미만
*7	갱의실입구	8:53 ~ 9:35	10.00	불검출[검출한계 0.002미만]	미만
*8	음압기배출구	8:53 ~ 9:35	10.00	불검출[검출한계 0.002미만]	미만
*9	폐기물반출구	11:02 ~ 11:44	10.00	0.003	미만
*10	작업장주변2	13:03 ~ 15:08	10.00	불검출[검출한계 0.002미만]	미만
*11	작업장주변3	15:33 ~ 17:38	10.00	불검출[검출한계 0.002미만]	미만
*12	폐기물보관1	17:06 ~ 17:48	10.00	0.003	미만
*13	폐기물보관2	17:10 ~ 17:52	10.00	0.003	미만
[비 고]					