


[별 첨1] 측정 위치도(측정 장소)



[별첨2] 측정 결과


측정위치		측정시간 (분)	유량 (ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과여부
*1	부지경계선1	8:00 ~ 12:05	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	8:05 ~ 12:10	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	8:10 ~ 12:15	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	8:15 ~ 12:20	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	8:20 ~ 8:00	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변	8:25 ~ 10:25	10.00	불검출[검출한계 0.002미만]	미만
*7	폐기물반출구	8:30 ~ 9:10	10.00	불검출[검출한계 0.002미만]	미만

[비 고]

[별첨3] 측정 사진

한화케미칼 CA-2 생산팀 셀룸 석면슬레이트 제거			
			
1. 부지경계선1	2. 부지경계선2	3. 부지경계선3	4. 부지경계선4
			
5. 위생설비입구	6. 작업장주변	7. 폐기물반출구	-



[별 첨1] 측정 위치도(측정 장소)




[별 첨2] 측정 결과

측정위치		측정시간 (분)	유량 (ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과여부
*1	부지경계선1	10:00 ~ 14:00	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	10:05 ~ 14:05	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	10:10 ~ 14:10	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	10:15 ~ 14:15	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	10:20 ~ 11:00	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변	10:25 ~ 12:25	10.00	불검출[검출한계 0.002미만]	미만
*7	폐기물반출구	10:30 ~ 11:10	10.00	0.003	미만
[비 고]					

[별첨3] 측정 사진

한화케미칼 CA-2 생산팀 셀룸 석면슬레이트 제거			
			
1. 부지경계선1	2. 부지경계선2	3. 부지경계선3	4. 부지경계선4
			
5. 위생설비입구	6. 작업장주변	7. 폐기물반출구	-

[별 첨1] 측정 위치도(측정 장소)



[별첨2] 측정 결과

측정위치		측정시간 (분)	유량 (ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과여부
*1	부지경계선1	9:40 ~ 13:40	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	9:42 ~ 13:42	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	9:45 ~ 13:45	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	9:48 ~ 13:48	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	10:10 ~ 10:50	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변	10:15 ~ 12:15	10.00	불검출[검출한계 0.002미만]	미만
*7	폐기물반출구	11:05 ~ 11:45	10.00	0.003	미만

[비 고]

[별첨3] 측정 사진

한화케미칼 CA-2 생산팀 셀룸 석면슬레이트 제거			
			
1. 부지경계선1	2. 부지경계선2	3. 부지경계선3	4. 부지경계선4
			-
5. 위생설비입구	6. 작업장 주변	7. 폐기물반출구	