


[별첨1] 측정 위치도(측정 장소)

한화케미칼 CA1 공정











범례	*NO		
	시료채취	대상건축물	부지경계선


[별첨2] 측정 결과

측정 결과					
측정위치		측정시간(분)	유량(ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과여부
*1	부지경계선1	13:50 ~ 16:20	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	13:52 ~ 16:22	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	13:54 ~ 16:24	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	13:56 ~ 16:26	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	14:00 ~ 14:40	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변	14:05 ~ 16:05	10.00	불검출[검출한계 0.002미만]	미만
*7	폐기물반출구1	13:50 ~ 14:30	10.00	불검출[검출한계 0.002미만]	미만
*8	폐기물반출구2	14:35 ~ 15:15	10.00	불검출[검출한계 0.002미만]	미만
*9	폐기물반출구3	15:20 ~ 16:00	10.00	불검출[검출한계 0.002미만]	미만
*10	폐기물반출구4	15:45 ~ 16:25	10.00	불검출[검출한계 0.002미만]	미만
[비 고]					

[별첨3] 측정 사진

측정 사진			
			
1. 부지경계선1	2. 부지경계선2	3. 부지경계선3	4. 부지경계선4
			
5. 위생설비입구	6. 작업장주변	7. 폐기물반출구1	8. 폐기물반출구2
			
9. 폐기물반출구3	10. 폐기물반출구4	-	-

[별 첨1] 측정 위치도(측정 장소)



[별첨2] 측정 결과

측정 결과					
측정위치		측정시간(분)	유량(ℓ/min)	측정농도 [기준: 0.01개/ cm^3]	초과여부
*1	부지경계선1	9:15 ~ 11:35	10.00	불검출[검출한계 0.002미만]	미만
*2	부지경계선2	9:17 ~ 11:37	10.00	불검출[검출한계 0.002미만]	미만
*3	부지경계선3	9:18 ~ 11:38	10.00	불검출[검출한계 0.002미만]	미만
*4	부지경계선4	9:20 ~ 11:40	10.00	불검출[검출한계 0.002미만]	미만
*5	위생설비입구	9:30 ~ 10:10	10.00	불검출[검출한계 0.002미만]	미만
*6	작업장주변	9:25 ~ 11:25	10.00	불검출[검출한계 0.002미만]	미만
*7	폐기물반출구1	9:25 ~ 10:05	10.00	불검출[검출한계 0.002미만]	미만
*8	폐기물반출구2	10:10 ~ 10:50	10.00	불검출[검출한계 0.002미만]	미만
*9	폐기물반출구3	11:00 ~ 11:40	10.00	불검출[검출한계 0.002미만]	미만
[비 고]					

[별첨3] 측정 사진

측정 사진			
			
1. 부지경계선1	2. 부지경계선2	3. 부지경계선3	4. 부지경계선4
			
5. 위생설비입구	6. 작업장주변	7. 폐기물반출구1	8. 폐기물반출구2
			
9. 폐기물반출구3	-	-	-