


★측정결과 [2020년 04월 28일]

[illegible]

[별첨 2]

★측정 지점 위치도(도식도) [2020년 04월 28일]











[별첨 3-1]
[2020년 04월 28일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 13:30	측정종료시간 : 17:10	
#2 부지경계			
	측정시작시간 : 13:31	측정종료시간 : 17:11	
#3 부지경계			
	측정시작시간 : 13:32	측정종료시간 : 17:13	
#4 부지경계			
	측정시작시간 : 13:33	측정종료시간 : 17:14	
#5 위생설비			
	측정시작시간 : 13:40	측정종료시간 : 14:25	

[별첨 3-2]
[2020년 04월 27일]

석면비산 농도측정 관련 사진


측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 음압기 배출구			
	측정시작시간 : 13:42	측정종료시간 : 14:30	
#7 음압기 배출구			
	측정시작시간 : 13:42	측정종료시간 : 14:30	
#8 작업장주변 (실내)			
	측정시작시간 : 14:15	측정종료시간 : 16:05	
#9 폐기물 반출구			
	측정시작시간 : 14:30	측정종료시간 : 15:06	

★측정결과 [2020년 05월 12일] - 작업시간 120분

[illegible]

[별첨 2]

★측정 지점 위치도(도식도) [2020년 05월 12일]













- 부지경계선
- 응압기배출구
- 위생설비
- 작업장주변(실내,외)
- 폐기물 반출구
- 폐기물 보관점
- 거주지 주거지역

[별첨 3-1]

[2020년 05월 12일]







석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 13:00	측정종료시간 : 15:20	
#2 부지경계			
	측정시작시간 : 13:01	측정종료시간 : 15:21	
#3 부지경계			
	측정시작시간 : 13:02	측정종료시간 : 15:22	
#4 부지경계			
	측정시작시간 : 13:02	측정종료시간 : 15:23	
#5 위생설비			
	측정시작시간 : 13:05	측정종료시간 : 13:45	

[별첨 3-2]

[2020년 05월 12일]

석면비산 농도측정 관련 사진


측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 작업장주변 (실내)			
	측정시작시간 : 13:30	측정종료시간 : 15:25	
#7 음압기 배출구			
	측정시작시간 : 13:10	측정종료시간 : 13:50	
#8 폐기물 반출구			
	측정시작시간 : 13:40	측정종료시간 : 14:16	

★측정결과 [2020년 05월 19일]

[illegible]

[별첨 2]

★측정 지점 위치도(도식도) [2020년 05월 19일]





- 부지경계선
- 음압기배출구
- 위생설비
- 작업장주변(실내,외)
- 폐기물 반출구
- 폐기물 보관점
- 거주자 주거지역

[별첨 3-1]











[2020년 05월 19일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 11:57	측정종료시간 : 15:28	
#2 부지경계			
	측정시작시간 : 11:58	측정종료시간 : 15:29	
#3 부지경계			
	측정시작시간 : 11:59	측정종료시간 : 15:30	
#4 부지경계			
	측정시작시간 : 12:00	측정종료시간 : 15:31	
#5 위생설비			
	측정시작시간 : 11:50	측정종료시간 : 12:30	

[별첨 3-2]
[2020년 05월 12일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 작업장주변 (실내)			
	측정시작시간 : 11:52	측정종료시간 : 13:42	
#7 음압기 배출구1			
	측정시작시간 : 11:54	측정종료시간 : 12:34	
#8 음압기 배출구2			
	측정시작시간 : 11:55	측정종료시간 : 12:35	
#9 음압기 배출구3			
	측정시작시간 : 11:55	측정종료시간 : 12:36	
#10 폐기물 반출구			
	측정시작시간 : 15:20	측정종료시간 : 15:57	

★측정결과 [2020년 05월 23일]

[illegible]

[별첨 2]











★측정 지점 위치도(도식도) [2020년 05월 23일]



- 부지경계선
- 음압기배출구
- 위험설비
- 작업장주변(실내,외)
- 폐기물 반출구
- 폐기물 보관점
- 거주자 주거지역







[별첨 3-1]
[2020년 05월 23일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 09:15	측정종료시간 : 13:00	
#2 부지경계			
	측정시작시간 : 09:16	측정종료시간 : 13:00	
#3 부지경계			
	측정시작시간 : 09:17	측정종료시간 : 13:01	
#4 부지경계			
	측정시작시간 : 09:18	측정종료시간 : 13:02	
#5 위생설비			
	측정시작시간 : 09:23	측정종료시간 : 10:03	

[별첨 3-2]
[2020년 05월 23일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 작업장주변 (실내)			
	측정시작시간 : 09:25	측정종료시간 : 11:15	
#7 음압기 배출구			
	측정시작시간 : 11:20	측정종료시간 : 12:00	
#8 폐기물 반출구			
	측정시작시간 : 13:05	측정종료시간 : 13:42	

★측정결과 [2020년 05월 30일]

[illegible]

[별첨 2]

★측정 지점 위치도(도식도) [2020년 05월 30일]



[별첨 3-1]











[2020년 05월 30일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 10:45	측정종료시간 : 15:00	
#2 부지경계			
	측정시작시간 : 10:46	측정종료시간 : 15:01	
#3 부지경계			
	측정시작시간 : 10:49	측정종료시간 : 15:05	
#4 부지경계			
	측정시작시간 : 10:50	측정종료시간 : 15:06	
#5 작업장주변 (실내)			
	측정시작시간 : 11:00	측정종료시간 : 13:00	







[별첨 3-2]
[2020년 05월 30일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 위생설비			
	측정시작시간 : 11:10	측정종료시간 : 11:50	
#7 음압기 배출구			
	측정시작시간 : 13:01	측정종료시간 : 13:41	
#8 음압기 배출구			
	측정시작시간 : 13:01	측정종료시간 : 13:41	
#9 음압기 배출구			
	측정시작시간 : 13:03	측정종료시간 : 13:42	
#10 음압기 배출구			
	측정시작시간 : 13:50	측정종료시간 : 14:26	

[별첨 3-3]
[2020년 05월 30일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#11 폐기물 반출구			
	측정시작시간 : 13:40	측정종료시간 : 14:17	
#12 폐기물 반출구			
	측정시작시간 : 13:42	측정종료시간 : 14:19	
#13 폐기물 반출구			
	측정시작시간 : 14:10	측정종료시간 : 14:46	

★측정결과 [2020년 06월 06일]

[illegible]











[별첨 2]

★측정 지점 위치도(도식도) [2020년 06월 06일]





[별첨 3-1]
[2020년 06월 06일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#1 부지경계			
	측정시작시간 : 08:15	측정종료시간 : 11:47	
#2 부지경계			
	측정시작시간 : 08:16	측정종료시간 : 11:48	
#3 부지경계			
	측정시작시간 : 08:18	측정종료시간 : 11:49	
#4 부지경계			
	측정시작시간 : 08:19	측정종료시간 : 11:50	
#5 위생설비			
	측정시작시간 : 08:45	측정종료시간 : 09:22	

[별첨 3-2]
[2020년 06월 06일]

석면비산 농도측정 관련 사진

측정지점	비산측정 시작 사진	비산측정 종료 사진	비고
#6 작업장주변 (실내)			
	측정시작시간 : 08:50	측정종료시간 : 10:40	
#7 음압기 배출구1			
	측정시작시간 : 09:30	측정종료시간 : 10:02	
#8 폐기물 반출구1			
	측정시작시간 : 09:40	측정종료시간 : 10:17	
#9 음압기 배출구2			
	측정시작시간 : 09:35	측정종료시간 : 10:18	
#10 폐기물 반출구2			
	측정시작시간 : 09:45	측정종료시간 : 10:23	