


[별 첨1] 측정 위치도(측정 장소)

문수주택단지 도로개설공사 지정폐기물 해체,철거



범 례	*NO	
	시료채취	부지경계선

[별첨2] 측정 결과

측정 결과				
측정위치	측정시간 (분)	유량 (ℓ/min)	측정농도 [기준: 0.01개/㎤]	초과여부
*1 부지경계선1	10:20 ~ 14:20	10.00	불검출[검출한계 0.002미만]	미만
*2 부지경계선2	10:22 ~ 14:22	10.00	불검출[검출한계 0.002미만]	미만
*3 부지경계선3	10:27 ~ 14:27	10.00	불검출[검출한계 0.002미만]	미만
*4 부지경계선4	10:29 ~ 14:29	10.00	불검출[검출한계 0.002미만]	미만
*5 위생설비입구	10:40 ~ 11:20	10.00	불검출[검출한계 0.002미만]	미만
*6 거주자주거지역1 (문수북11길 8앞 사거리)	10:34 ~ 12:34	10.00	불검출[검출한계 0.002미만]	미만
*7 거주자주거지역2 (문수북11길 8-29앞 사거리)	10:37 ~ 12:37	10.00	불검출[검출한계 0.002미만]	미만
*8 작업장주변1 (문수북11길 8-11,8-19,8-21,8-25)	10:32 ~ 11:32	10.00	불검출[검출한계 0.002미만]	미만
*9 작업장주변2 (문수북2길 28-9,28-7)	11:35 ~ 13:35	10.00	불검출[검출한계 0.002미만]	미만
*10 작업장주변3 (문수북1길 36-7)	13:38 ~ 13:48	10.00	불검출[검출한계 0.002미만]	미만
*11 작업장주변4 (문수북6길 21-1,21-2)	13:55 ~ 15:00	10.00	불검출[검출한계 0.002미만]	미만
*12 폐기물반출구	14:11 ~ 14:51	10.00	불검출[검출한계 0.002미만]	미만
*13 폐기물보관지점	15:01 ~ 15:41	10.00	불검출[검출한계 0.002미만]	미만
[비 고]				

[별첨3] 측정 사진

측정 사진			
			
*1. 부지경계선1	*2. 부지경계선2	*3. 부지경계선3	*4. 부지경계선4
			
*5. 위생설비입구	*6. 거주자주거지역1 (문수북11길 8앞 사거리)	*7. 거주자주거지역1 (문수북11길 8-29앞 사거리)	*8. 작업장주변1 (문수북11길 8-11,8-19,8-21,8-25)
			
*9. 작업장주변2 (문수북2길 28-9,28-17)	*10. 작업장주변3 (문수북1길 36-7)	*11. 작업장주변4 (문수북6길 21-1,21-2)	*12. 폐기물반출구
			
*13. 폐기물보관지점	-	-	-

[별 첨1] 측정 위치도(측정 장소)



[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
5	거주자주거지역1	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
6	거주자주거지역2	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
7	위생설비입구	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
8	작업장주변	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
9	음압기배출구1	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
10	음압기배출구2	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
11	음압기배출구3	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
12	음압기배출구4	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
13	음압기배출구5	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
14	폐기물반출구1	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
15	폐기물반출구2	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	0.003	-
16	폐기물반출구3	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	0.003	-
17	폐기물보관지점1	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
18	폐기물보관지점2	지역시료채취펌프 (SARA-5100)	1	10.00	20/06/09	불검출 [검출한계 0.002미만]	-
-	공시료	지역시료채취펌프 (SARA-5100)	1	-	-	0개/100개 시야	-
-	공시료	지역시료채취펌프 (SARA-5100)	1	-	-	0개/100개 시야	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선1 부지경계선2				
	8:30	12:30	8:35	12:35
부지경계선3 부지경계선4				
	8:40	12:40	8:45	12:45
가주자주거지역1 가주자주거지역2				
	8:50	10:50	8:55	10:55
위생설비입구 작업장 주변				
	9:00	9:40	9:01	11:01
음압기배출구1 음압기배출구2				
	9:10	9:50	9:45	10:25
음압기배출구3 음압기배출구4				
	9:45	10:25	13:00	13:40

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구5 폐기물반출구1				
	13:00	13:40	9:10	9:50
폐기물반출구2 폐기물반출구3				
	9:45	10:25	13:05	13:45
폐기물보관지점1 폐기물보관지점2				
	16:00	16:40	16:00	16:40