


[별첨1] 측정 위치도(측정 장소)



[별첨2] 측정 결과

[illegible]


[별첨3] 측정 사진



측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	9:00	13:10	9:05	13:15
부지경계선 3,4				
	9:10	13:20	9:15	13:25
위생설비 입구 / 작업장주변1				
	9:30	10:15	9:40	11:50
작업장주변2 / 폐기물반출구1				
	13:20	15:30	9:45	10:30
폐기물반출구2 / 거주자 주거지역1				
	13:25	14:10	10:45	12:55
거주자 주거지역2 / 폐기물 보관지점1				
	10:46	12:56	14:30	15:15

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물 보관지점2				
	14:35	15:20	-	-

[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사(1차)



























범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과

[illegible]

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2	 8:50	 13:00	 8:55	 13:05
부지경계선 3,4	 9:00	 13:10	 9:05	 13:15
위생설비 입구 / 작업장주변1	 9:20	 10:05	 9:35	 11:45
작업장주변2 / 폐기물반출구1	 11:20	 13:30	 9:40	 10:25
폐기물반출구2 / 거주자 주거지역1	 11:25	 12:10	 10:40	 12:50
거주자 주거지역2 / 폐기물 보관지점1	 10:42	 12:52	 13:30	 14:15

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물 보관지점2,3				
	13:35	14:20	13:40	14:25