

[별 첨 1] 측정 위치도(측정 장소)



[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	9.77	21/12/08	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	9.67	21/12/08	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	9.69	21/12/08	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	9.91	21/12/08	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	9.63	21/12/08	불검출 [검출한계 0.002미만]	-
6	갱의실1 (거북선공원길 6-5층)	지역시료채취펌프 (SARA-5100)	1	9.88	21/12/08	불검출 [검출한계 0.002미만]	-
7	갱의실2 (거북선공원길 6-4층)	지역시료채취펌프 (SARA-5100)	1	9.59	21/12/08	불검출 [검출한계 0.002미만]	-
8	작업장주변	지역시료채취펌프 (SARA-5100)	1	9.72	21/12/08	불검출 [검출한계 0.002미만]	-
9	음압기배출구1 (거북선공원길 6-5층)	지역시료채취펌프 (SARA-5100)	1	9.86	21/12/08	불검출 [검출한계 0.002미만]	-
10	음압기배출구2 (거북선공원길 6-5층)	지역시료채취펌프 (SARA-5100)	1	9.56	21/12/08	불검출 [검출한계 0.002미만]	-
11	음압기배출구3 (거북선공원길 6-4층)	지역시료채취펌프 (SARA-5100)	1	9.59	21/12/08	불검출 [검출한계 0.002미만]	-
12	음압기배출구4 (거북선공원길 6-4층)	지역시료채취펌프 (SARA-5100)	1	9.86	21/12/08	불검출 [검출한계 0.002미만]	-
13	폐기물반출구1 (거북선공원길 6-5층)	지역시료채취펌프 (SARA-5100)	1	9.83	21/12/08	불검출 [검출한계 0.002미만]	-
14	폐기물반출구2 (거북선공원길 6-4층)	지역시료채취펌프 (SARA-5100)	1	9.99	21/12/08	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개 시야	-
-	공시료	-	-	-	-	0개/100개 시야	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:30	12:40	8:35	12:45
부지경계선 3,4				
	8:40	12:50	8:45	12:55
위생설비 입구 / 갱의실1 (거북선공원3길 6 - 5층)				
	9:00	9:45	10:10	10:55
갱의실2 (거북선공원3길 6 - 4층) / 작업장주변				
	11:15	12:00	10:00	12:10
음압기배 출구1 (거북선공원3길 6 - 5층) / 음압기배 출구2 (거북선공원3길 6 - 5층)				
	10:12	10:57	10:13	10:58

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구3 (거북선공원3길 6 - 4층) /				
음압기배출구4 (거북선공원3길 6 - 4층)	11:16	12:01	11:17	12:02
폐기물반출구1 (거북선공원3길 6 - 5층) /				
폐기물반출구2 (거북선공원3길 6 - 4층)	13:05	13:50	14:15	15:00

[별첨1] 측정 위치도(측정 장소)

여수시 학동 골드클래스 현장 중 석면해체제거공사



50 레	*NO		
	시료채취	부지경계선	해당건물












[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	9.76	21/12/09	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	9.78	21/12/09	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	9.85	21/12/09	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	9.93	21/12/09	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	9.71	21/12/09	불검출 [검출한계 0.002미만]	-
6	갱의실1 (거북선공원3길 6-3층)	지역시료채취펌프 (SARA-5100)	1	9.92	21/12/09	불검출 [검출한계 0.002미만]	-
7	갱의실2 (거북선공원3길 6-3층 참고)	지역시료채취펌프 (SARA-5100)	1	9.80	21/12/09	불검출 [검출한계 0.002미만]	-
8	갱의실3 (거북선공원3길 6-2층)	지역시료채취펌프 (SARA-5100)	1	9.60	21/12/09	불검출 [검출한계 0.002미만]	-
9	갱의실4 (거북선공원3길 6-2층 참고1)	지역시료채취펌프 (SARA-5100)	1	9.79	21/12/09	불검출 [검출한계 0.002미만]	-
10	작업장주변	지역시료채취펌프 (SARA-5100)	1	9.59	21/12/09	불검출 [검출한계 0.002미만]	-
11	음압기배출구1 (거북선공원3길 6-3층)	지역시료채취펌프 (SARA-5100)	1	9.90	21/12/09	불검출 [검출한계 0.002미만]	-
12	음압기배출구2 (거북선공원3길 6-3층)	지역시료채취펌프 (SARA-5100)	1	9.55	21/12/09	불검출 [검출한계 0.002미만]	-
13	음압기배출구3 (거북선공원3길 6-3층 참고)	지역시료채취펌프 (SARA-5100)	1	9.98	21/12/09	불검출 [검출한계 0.002미만]	-
14	음압기배출구4 (거북선공원3길 6-2층)	지역시료채취펌프 (SARA-5100)	1	9.84	21/12/09	불검출 [검출한계 0.002미만]	-
15	음압기배출구5 (거북선공원3길 6-2층)	지역시료채취펌프 (SARA-5100)	1	9.71	21/12/09	불검출 [검출한계 0.002미만]	-
16	음압기배출구6 (거북선공원3길 6-2층 참고1)	지역시료채취펌프 (SARA-5100)	1	9.69	21/12/09	불검출 [검출한계 0.002미만]	-
17	폐기물반출구1 (거북선공원3길 6-3층)	지역시료채취펌프 (SARA-5100)	1	9.70	21/12/09	불검출 [검출한계 0.002미만]	-
18	폐기물반출구2 (거북선공원3길 6-3층 참고)	지역시료채취펌프 (SARA-5100)	1	9.74	21/12/09	불검출 [검출한계 0.002미만]	-

19	폐기물반출구3 (거북선공원길 6-2층)	지역시료채취펌프 (SARA-5100)	1	9.56	21/12/09	불검출 [검출한계 0.002미만]	-
20	폐기물반출구4 (거북선공원3길 6 - 2층 참고1)	지역시료채취펌프 (SARA-5100)	1	9.85	21/12/09	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개 시야	-
-	공시료	-	-	-	-	0개/100개 시야	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:45	12:55	8:50	13:00
부지경계선 3,4				
	8:55	13:05	9:00	13:10
위생설비 입구 / 갱의실1 (거북선공원3길 6 - 3층)				
	9:10	9:55	9:30	10:15
갱의실2 (거북선공원3길 6 - 3층 창고) / 갱의실3 (거북선공원3길 6 - 2층)				
	9:31	10:16	10:30	11:15
갱의실4 (거북선공원3길 6 - 2층 창고1) / 작업장주변				
	10:32	11:17	10:00	12:10

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구1 (거북선공원3길 6 - 3층) /				
음압기배출구2 (거북선공원3길 6 - 3층)	9:33	10:18	9:34	10:19
음압기배출구3 (거북선공원3길 6 - 3층 참고) /				
음압기배출구4 (거북선공원3길 6 - 2층)	9:35	10:20	10:35	11:20
음압기배출구5 (거북선공원3길 6 - 2층) /				
음압기배출구6 (거북선공원3길 6 - 2층 참고1)	10:36	11:21	10:38	11:23
폐기물반출구1 (거북선공원3길 6 - 3층) /				
폐기물반출구2 (거북선공원3길 6 - 3층 참고)	13:00	13:45	13:05	13:50
폐기물반출구3 (거북선공원3길 6 - 2층) /				
폐기물반출구4 (거북선공원3길 6 - 2층 참고1)	14:05	14:50	14:10	14:55

여수시 학동 골드클래스 현장 중 석면해체제거공사









범 례	*NO	<div></div>	<div></div>
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	9.82	21/12/10	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	9.68	21/12/10	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	9.74	21/12/10	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	9.81	21/12/10	불검출 [검출한계 0.002미만]	-
5	위생설비입구1	지역시료채취펌프 (SARA-5100)	1	9.86	21/12/10	불검출 [검출한계 0.002미만]	-
6	위생설비입구2	지역시료채취펌프 (SARA-5100)	1	9.59	21/12/10	불검출 [검출한계 0.002미만]	-
7	작업장주변1	지역시료채취펌프 (SARA-5100)	1	9.62	21/12/10	불검출 [검출한계 0.002미만]	-
8	작업장주변2	지역시료채취펌프 (SARA-5100)	1	9.93	21/12/10	불검출 [검출한계 0.002미만]	-
9	음압기배출구1 (거북선공원3길 6-1층)	지역시료채취펌프 (SARA-5100)	1	9.83	21/12/10	불검출 [검출한계 0.002미만]	-
10	음압기배출구2 (거북선공원3길 6-1층)	지역시료채취펌프 (SARA-5100)	1	9.85	21/12/10	불검출 [검출한계 0.002미만]	-
11	음압기배출구3 (거북선공원3길 12-1층 창고)	지역시료채취펌프 (SARA-5100)	1	9.51	21/12/10	불검출 [검출한계 0.002미만]	-
12	폐기물반출구1 (거북선공원3길 6-1층)	지역시료채취펌프 (SARA-5100)	1	9.70	21/12/10	불검출 [검출한계 0.002미만]	-
13	폐기물반출구2 (거북선공원3길 12-1층 창고)	지역시료채취펌프 (SARA-5100)	1	9.78	21/12/10	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:35	12:45	8:40	12:50
부지경계선 3,4				
	8:45	12:55	8:50	13:00
위생설비 입구 1,2				
	9:00	9:45	10:00	10:45
작업장주변 1,2				
	9:05	11:15	10:10	12:20
음압기배출구1 (거북선공원3길 6 - 1층) / 음압기배출구2 (거북선공원3길 6- 1층)				
	9:10	9:55	9:11	9:56

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구3 (거북선공원길 12-1 - 1층 창고) / 폐기물반출구1 (거북선공원길 6-1층)				
	10:03	10:48	11:20	12:05
폐기물반출구2 (거북선공원길 12-1 - 1층 창고)				
	11:40	12:25	-	-