


[별첨1] 측정 위치도(측정 장소)

소호동 여천자동차학원 건축물 철거공사 중 석면철거공사






범례	*NO		
	시료채취	부지경계선	해당건물

[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
6	작업장주변	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
7	음압기배출구1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
8	음압기배출구2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
9	음압기배출구3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
10	음압기배출구4	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
11	음압기배출구5	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
12	음압기배출구6	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
13	폐기물반출구1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
14	폐기물반출구2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
15	폐기물반출구3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
16	폐기물반출구4	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
17	폐기물반출구5	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
18	폐기물반출구6	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/16	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선1,2	 8:00	 12:00	 8:03	 12:03
부지경계선3,4	 8:08	 12:08	 8:11	 12:11
위생설비입구 / 작업장주변	 8:15	 8:55	 8:18	 10:18
응압기배출구1,2	 8:23	 9:03	 8:24	 9:04
응압기배출구3,4	 8:26	 9:06	 8:40	 9:20

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구5,6				
	8:42	9:22	8:45	9:25
폐기물반출구1,2				
	10:00	10:40	10:02	10:42
폐기물반출구3,4				
	10:05	10:45	10:20	11:00
폐기물반출구5,6				
	10:22	11:02	10:25	11:05

[별첨1] 측정 위치도(측정 장소)





[별첨2] 측정 결과

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
1	부지경계선1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
2	부지경계선2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
3	부지경계선3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
4	부지경계선4	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
5	위생설비입구	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
6	작업장주변	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
7	음압기배출구1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
8	음압기배출구2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
9	음압기배출구3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
10	음압기배출구4	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
11	음압기배출구5	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
12	음압기배출구6	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
13	폐기물반출구1	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
14	폐기물반출구2	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
15	폐기물반출구3	지역시료채취펌프 (SARA-5100)	1	10.00	21/04/15	불검출 [검출한계 0.002미만]	-
-	공시료	-	-	-	-	-	-
-	공시료	-	-	-	-	-	-

[별첨3] 측정 사진

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선1,2				
	11:00	15:00	11:02	15:02
부지경계선3,4				
	11:05	15:05	11:07	15:07
위생설비입구 / 작업장주변				
	11:12	11:52	11:15	13:15
응압기배출구1,2				
	11:20	12:00	11:22	12:02
응압기배출구3,4				
	11:23	12:03	11:30	12:10

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
음압기배출구5,6				
	11:33	12:13	11:34	12:14
폐기물반출구1,2				
	11:40	12:20	11:42	12:22
폐기물반출구3				
	11:45	12:25	-	-