



[별 첨1] 측정 위치도(측정 장소)













소제지구 택지개발공사 중 석면철거공사	측정일시	22.9.16	
			
범 례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.16)

[illegible]

[별첨3] 측정 사진 (측정일시 22.9.16)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선1,2				
	10:30	14:40	10:35	14:45
부지경계선 3,4				
	10:40	14:50	10:45	14:55
거주자 주거지역 1,2				
	10:55	13:05	11:00	13:10
위생설비입구 작업장주변1				
	11:05	11:50	11:10	13:20
작업장주변2 폐기물반출구1				
	13:40	15:50	11:20	12:05
폐기물반출구 2,3				
	11:40	12:25	14:00	14:45

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물반출구4 폐기물보관지점1				
	15:00	15:45	16:00	16:45
폐기물보관지점 2,3				
	16:00	16:45	16:30	17:15
폐기물보관지점4				
	16:30	17:15	-	-

[별첨1] 측정 위치도(측정 장소)





























[별첨2] 측정 결과 (측정일시 22.9.17)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	9.82	22/09/17	불검출[검출한계 0.002미만]	-
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.84	22/09/17	불검출[검출한계 0.002미만]	-
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	9.84	22/09/17	불검출[검출한계 0.002미만]	-
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.86	22/09/17	불검출[검출한계 0.002미만]	-
*5	거주자주거지역1	지역시료채취펌프 SARA-5100	1	9.68	22/09/17	불검출[검출한계 0.002미만]	-
*6	거주자주거지역2	지역시료채취펌프 SARA-5100	1	9.73	22/09/17	불검출[검출한계 0.002미만]	-
*7	위생설비입구1	지역시료채취펌프 SARA-5100	1	9.59	22/09/17	불검출[검출한계 0.002미만]	-
*8	위생설비입구2	지역시료채취펌프 SARA-5100	1	9.74	22/09/17	불검출[검출한계 0.002미만]	-
*9	작업장주변1	지역시료채취펌프 SARA-5100	1	9.68	22/09/17	불검출[검출한계 0.002미만]	-
*10	작업장주변2	지역시료채취펌프 SARA-5100	1	9.99	22/09/17	불검출[검출한계 0.002미만]	-
*11	작업장주변3	지역시료채취펌프 SARA-5100	1	9.80	22/09/17	불검출[검출한계 0.002미만]	-
*12	폐기물반출구1	지역시료채취펌프 SARA-5100	1	9.97	22/09/17	불검출[검출한계 0.002미만]	-
*13	폐기물반출구2	지역시료채취펌프 SARA-5100	1	9.88	22/09/17	불검출[검출한계 0.002미만]	-
*14	폐기물반출구3	지역시료채취펌프 SARA-5100	1	9.84	22/09/17	불검출[검출한계 0.002미만]	-
*15	폐기물반출구4	지역시료채취펌프 SARA-5100	1	9.74	22/09/17	불검출[검출한계 0.002미만]	-

[illegible]

[별첨3] 측정 사진 (측정일시 22.9.17)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:00	12:10	8:15	12:25
부지경계선 3,4				
	8:20	12:30	8:25	12:35
거주지주거지역 1,2				
	8:40	10:50	8:45	10:55
위생설비입구 1,2				
	8:10	8:55	9:30	10:15
작업장주변 1,2				
	8:05	10:15	9:00	11:10
작업장주변3 폐기물반출구1				
	9:30	11:40	8:08	8:53

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물반출구 2,3				
	9:15	10:00	10:00	10:45
폐기물반출구4 폐기물보관지점1				
	13:00	13:45	15:30	16:15
폐기물보관지점 2,3				
	15:30	16:15	15:40	16:25
폐기물보관지점 4,5				
	15:40	16:25	16:00	16:45
폐기물보지점 6				
	16:00	16:45	-	-





[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.18
			
범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.18)

[illegible]

[별첨3] 측정 사진 (측정일시 22.9.18)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	9:00	9:45	9:00	9:45
폐기물보관지점 3,4				
	9:10	9:55	9:10	9:55
폐기물보관지점 5,6				
	9:20	10:05	9:20	10:05













[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.19
			
범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.19)

[illegible]

[별첨3] 측정 사진 (측정일시 22.9.19)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	9:30	10:15	9:30	10:15
폐기물보관지점 3,4				
	9:35	10:20	9:35	10:20
폐기물보관지점 5,6				
	9:40	10:25	9:40	10:25

[별첨1] 측정 위치도(측정 장소)

























소제지구 택지개발공사 중 석면철거공사		측정일시		22.9.20	
					
범례	*NO				
	시료채취	부지경계선	대상건축물		
























[별첨2] 측정 결과 (측정일시 22.9.20)

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (l/분)	측정 일시	측정 결과 (f/cc)	비고
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	9.78	22/09/20	불검출[검출한계 0.002미만]	-
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.97	22/09/20	불검출[검출한계 0.002미만]	-
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	9.88	22/09/20	불검출[검출한계 0.002미만]	-
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.84	22/09/20	불검출[검출한계 0.002미만]	-
*5	거주자주거지역1	지역시료채취펌프 SARA-5100	1	9.58	22/09/20	불검출[검출한계 0.002미만]	-
*6	거주자주거지역2	지역시료채취펌프 SARA-5100	1	9.97	22/09/20	불검출[검출한계 0.002미만]	-
*7	위생설비입구1	지역시료채취펌프 SARA-5100	1	9.75	22/09/20	불검출[검출한계 0.002미만]	-
*8	위생설비입구2	지역시료채취펌프 SARA-5100	1	9.89	22/09/20	불검출[검출한계 0.002미만]	-
*9	위생설비입구3	지역시료채취펌프 SARA-5100	1	9.99	22/09/20	불검출[검출한계 0.002미만]	-
*10	작업장주변1	지역시료채취펌프 SARA-5100	1	9.81	22/09/20	불검출[검출한계 0.002미만]	-
*11	작업장주변2	지역시료채취펌프 SARA-5100	1	9.57	22/09/20	불검출[검출한계 0.002미만]	-
*12	작업장주변3	지역시료채취펌프 SARA-5100	1	9.80	22/09/20	불검출[검출한계 0.002미만]	-
*13	폐기물반출구1	지역시료채취펌프 SARA-5100	1	9.71	22/09/20	불검출[검출한계 0.002미만]	-
*14	폐기물반출구2	지역시료채취펌프 SARA-5100	1	9.50	22/09/20	불검출[검출한계 0.002미만]	-
*15	폐기물반출구3	지역시료채취펌프 SARA-5100	1	9.82	22/09/20	불검출[검출한계 0.002미만]	-
*16	폐기물반출구4	지역시료채취펌프 SARA-5100	1	9.80	22/09/20	불검출[검출한계 0.002미만]	-
*17	폐기물반출구5	지역시료채취펌프 SARA-5100	1	9.55	22/09/20	불검출[검출한계 0.002미만]	-
*18	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.59	22/09/20	불검출[검출한계 0.002미만]	-
*19	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.59	22/09/20	불검출[검출한계 0.002미만]	-
*20	폐기물보관지점3	지역시료채취펌프 SARA-5100	1	9.91	22/09/20	불검출[검출한계 0.002미만]	-

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*21	폐기물보관지점4	지역시료채취펌프 SARA-5100	1	9.73	22/09/20	불검출[검출한계 0.002미만]	-
*22	폐기물보관지점5	지역시료채취펌프 SARA-5100	1	9.69	22/09/20	불검출[검출한계 0.002미만]	-
*23	폐기물보관지점6	지역시료채취펌프 SARA-5100	1	9.78	22/09/20	불검출[검출한계 0.002미만]	-
*24	폐기물보관지점7	지역시료채취펌프 SARA-5100	1	10.00	22/09/20	불검출[검출한계 0.002미만]	-
*25	폐기물보관지점8	지역시료채취펌프 SARA-5100	1	9.58	22/09/20	불검출[검출한계 0.002미만]	-
*26	폐기물보관지점9	지역시료채취펌프 SARA-5100	1	9.78	22/09/20	불검출[검출한계 0.002미만]	-
*27	폐기물보관지점10	지역시료채취펌프 SARA-5100	1	9.92	22/09/20	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진 (측정일시 22.9.20)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:00	12:10	8:05	12:15
부지경계선 3,4				
	8:10	12:20	8:15	12:25
거주지주거지역 1,2				
	8:20	10:30	8:25	10:35
위생설비입구 1,2				
	8:30	9:15	9:00	9:45
위생설비입구3 작업장주변1				
	9:30	10:15	8:35	10:45
작업장주변 2,3				
	9:05	11:15	9:35	11:45

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물반출구 1,2	 8:40	 9:25	 9:10	 9:55
폐기물반출구 3,4	 9:40	 10:25	 13:00	 13:45
폐기물반출구5 폐기물보관지점1	 13:10	 13:55	 15:00	 15:45
폐기물보관지점 2,3	 15:00	 15:45	 15:05	 15:50
폐기물보관지점 4,5	 15:05	 15:50	 15:10	 15:55
폐기물보관지점 6,7	 15:10	 15:55	 15:15	 16:00

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 8,9	 15:15	 16:00	 15:20	 16:05
폐기물보관지점 10	 15:20	 16:05	 —	 —

[별 첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사	측정일시	22.9.21
----------------------	------	---------













범 례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.21)

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	9.77	22/09/21	불검출[검출한계 0.002미만]	-
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.71	22/09/21	불검출[검출한계 0.002미만]	-
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	9.75	22/09/21	불검출[검출한계 0.002미만]	-
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.77	22/09/21	불검출[검출한계 0.002미만]	-
*5	거주자주거지역1	지역시료채취펌프 SARA-5100	1	9.76	22/09/21	불검출[검출한계 0.002미만]	-
*6	거주자주거지역2	지역시료채취펌프 SARA-5100	1	9.61	22/09/21	불검출[검출한계 0.002미만]	-
*7	위생설비입구1	지역시료채취펌프 SARA-5100	1	9.97	22/09/21	불검출[검출한계 0.002미만]	-
*8	위생설비입구2	지역시료채취펌프 SARA-5100	1	9.90	22/09/21	불검출[검출한계 0.002미만]	-
*9	위생설비입구3	지역시료채취펌프 SARA-5100	1	9.77	22/09/21	불검출[검출한계 0.002미만]	-
*10	작업장주변1	지역시료채취펌프 SARA-5100	1	9.68	22/09/21	불검출[검출한계 0.002미만]	-
*11	작업장주변2	지역시료채취펌프 SARA-5100	1	9.93	22/09/21	불검출[검출한계 0.002미만]	-
*12	작업장주변3	지역시료채취펌프 SARA-5100	1	9.50	22/09/21	불검출[검출한계 0.002미만]	-
*13	폐기물반출구1	지역시료채취펌프 SARA-5100	1	9.68	22/09/21	불검출[검출한계 0.002미만]	-
*14	폐기물반출구2	지역시료채취펌프 SARA-5100	1	9.58	22/09/21	불검출[검출한계 0.002미만]	-
*15	폐기물반출구3	지역시료채취펌프 SARA-5100	1	9.83	22/09/21	불검출[검출한계 0.002미만]	-
*16	폐기물반출구4	지역시료채취펌프 SARA-5100	1	9.90	22/09/21	불검출[검출한계 0.002미만]	-
*17	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.63	22/09/21	불검출[검출한계 0.002미만]	-
*18	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.77	22/09/21	불검출[검출한계 0.002미만]	-
*19	폐기물보관지점3	지역시료채취펌프 SARA-5100	1	9.68	22/09/21	불검출[검출한계 0.002미만]	-
*20	폐기물보관지점4	지역시료채취펌프 SARA-5100	1	9.76	22/09/21	불검출[검출한계 0.002미만]	-

시료 번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고	
*21	폐기물보관지점5	지역시료채취펌프 SARA-5100	1	9.64	22/09/21	불검출[검출한계 0.002미만]	-
*22	폐기물보관지점6	지역시료채취펌프 SARA-5100	1	9.95	22/09/21	불검출[검출한계 0.002미만]	-
*23	폐기물보관지점7	지역시료채취펌프 SARA-5100	1	9.90	22/09/21	불검출[검출한계 0.002미만]	-
*24	폐기물보관지점8	지역시료채취펌프 SARA-5100	1	9.84	22/09/21	불검출[검출한계 0.002미만]	-
*25	폐기물보관지점9	지역시료채취펌프 SARA-5100	1	9.55	22/09/21	불검출[검출한계 0.002미만]	-
*26	폐기물보관지점10	지역시료채취펌프 SARA-5100	1	9.57	22/09/21	불검출[검출한계 0.002미만]	-
*27	폐기물보관지점11	지역시료채취펌프 SARA-5100	1	9.90	22/09/21	불검출[검출한계 0.002미만]	-
*28	폐기물보관지점12	지역시료채취펌프 SARA-5100	1	9.82	22/09/21	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진 (측정일시 22.9.21)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2				
	8:00	12:10	8:05	12:15
부지경계선 3,4				
	8:10	12:20	8:15	12:25
거주지주거지역 1,2				
	8:20	10:30	8:25	10:35
위생설비입구 1,2				
	8:30	9:15	9:00	9:45
위생설비입구3 작업장주변1				
	9:20	10:05	8:32	10:42
작업장주변 2,3				
	9:05	11:15	9:23	11:33

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물반출구 1,2				
	9:20	10:05	9:50	10:35
폐기물반출구 3,4				
	10:10	10:55	13:00	13:45
폐기물보관지점 1,2				
	14:30	15:15	14:30	15:15
폐기물보관지점 3,4				
	14:35	15:20	14:35	15:20
폐기물보관지점 5,6				
	14:40	15:25	14:40	15:25
폐기물보관지점 7,8				
	14:45	15:30	14:45	15:30

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 9, 10				
	14:50	15:35	14:50	15:35
폐기물보관지점 11, 12				
	14:55	15:40	14:55	15:40

























[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.22
			
범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.22)




시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
*1	부지경계선1	지역시료채취펌프 SARA-5100	1	9.95	22/09/22	불검출[검출한계 0.002미만]	-
*2	부지경계선2	지역시료채취펌프 SARA-5100	1	9.89	22/09/22	불검출[검출한계 0.002미만]	-
*3	부지경계선3	지역시료채취펌프 SARA-5100	1	9.89	22/09/22	불검출[검출한계 0.002미만]	-
*4	부지경계선4	지역시료채취펌프 SARA-5100	1	9.79	22/09/22	불검출[검출한계 0.002미만]	-
*5	거주자주거지역1	지역시료채취펌프 SARA-5100	1	9.72	22/09/22	불검출[검출한계 0.002미만]	-
*6	거주자주거지역2	지역시료채취펌프 SARA-5100	1	9.87	22/09/22	불검출[검출한계 0.002미만]	-
*7	위생설비입구	지역시료채취펌프 SARA-5100	1	9.74	22/09/22	불검출[검출한계 0.002미만]	-
*8	작업장주변	지역시료채취펌프 SARA-5100	1	9.76	22/09/22	불검출[검출한계 0.002미만]	-
*9	음압기배출구1	지역시료채취펌프 SARA-5100	1	9.63	22/09/22	불검출[검출한계 0.002미만]	-
*10	음압기배출구2	지역시료채취펌프 SARA-5100	1	10.00	22/09/22	불검출[검출한계 0.002미만]	-
*11	폐기물반출구	지역시료채취펌프 SARA-5100	1	9.90	22/09/22	불검출[검출한계 0.002미만]	-
*12	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.88	22/09/22	불검출[검출한계 0.002미만]	-
*13	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.95	22/09/22	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개 시야	-
-	공시료	-	-	-	-	0개/100개 시야	-

[별첨3] 측정 사진 (측정일시 22.9.22)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
부지경계선 1,2	 8:00	 12:10	 8:05	 12:15
부지경계선 3,4	 8:10	 12:20	 8:15	 12:25
거주자주거지역 1,2	 8:20	 10:30	 8:25	 10:35
위생설비입구 작업장주변	 8:30	 9:15	 8:35	 10:45
음압기배출구 1,2	 8:40	 9:25	 8:45	 9:30
폐기물반출구 폐기물보관장주변	 8:50	 9:35	 14:00	 14:45

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점2				
	14:00	14:45	-	-

[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.23
<div></div>			
범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.23)

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
*1	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.52	22/09/23	불검출[검출한계 0.002미만]	-
*2	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.58	22/09/23	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진 (측정일시 22.9.23)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	10:00	10:45	10:00	10:45

[별첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.24
범례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.24)

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
*1	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.90	22/09/24	불검출[검출한계 0.002미만]	-
*2	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	8.89	22/09/24	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진 (측정일시 22.9.24)

측정 지점	시작 사진		종료 사진	
폐기물보관지점 1,2				
	9:50		10:35	
				
	9:50		10:35	

[별 첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.25
범 례	*NO		
	시료채취	부지경계선	대상건축물




[별첨2] 측정 결과 (측정일시 22.9.25)

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
*1	폐기물보관지점 1	지역시료채취펌프 SARA-5100	1	9.64	22/09/25	불검출[검출한계 0.002미만]	-
*2	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.56	22/09/25	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개시야	-
-	공시료	-	-	-	-	0개/100개시야	-

[별첨3] 측정 사진 (측정일시 22.9.25)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	16:00	16:45	16:00	16:45

[별 첨1] 측정 위치도(측정 장소)

소제지구 택지개발공사 중 석면철거공사		측정일시	22.9.26
			
범 례	*NO		
	시료채취	부지경계선	대상건축물

[별첨2] 측정 결과 (측정일시 22.9.26)

시료 번호	측정 지점	측정 장비 (종류/수량)		유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	비고
*1	폐기물보관지점1	지역시료채취펌프 SARA-5100	1	9.71	22/09/26	불검출[검출한계 0.002미만]	-
*2	폐기물보관지점2	지역시료채취펌프 SARA-5100	1	9.50	22/09/26	불검출[검출한계 0.002미만]	-
-	공시료	-	-	-	-	0개/100개 시야	-
-	공시료	-	-	-	-	0개/100개 시야	-

[별첨3] 측정 사진 (측정일시 22.9.26)

측정 지점	시작 사진	종료 사진	시작 사진	종료 사진
폐기물보관지점 1,2				
	8:30	9:15	8:30	9:15